

Supplemental Type Certificate

Number SR00489SE

This certificate, issued to **Paravion Technology, Inc.
2001 Airway Avenue
Fort Collins, CO 80524**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product—Type Certificate Number: H2SW

Make: Bell

Model: 407

Description of the Type Design Change: Installation of an air conditioning system per Paravion Master Drawing List DL-407AC-110, Revision A, dated November 24, 1997, or later Federal Aviation Administration (FAA) approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to other aircraft on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate along with a copy of Paravion Rotorcraft Flight Manual Supplement PR-407AC-110M, Revision 0, dated December 5, 1997, and Instructions for Continued Airworthiness PR-407AC-120M, Revision 1, dated December 5, 1997, or later FAA approved revisions, must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 3, 1996

Date reissued:

Date of issuance: December 5, 1997

Date amended:



By direction of the Administrator

(Signature)

Acting Manager, Seattle
Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.